

Topic

Follett Corp. constantly strives to improve product quality through continuous improvement initiatives. Recently, the control board for the Maestro 400 lb. icemaker has been updated. This update includes a color change and a software revision. The service part number is 502331.

Updates

- 1. Color Change:** The control board's color has been changed from red to blue. The blue board is a direct replacement for the red board and is backward compatible.
- 2. Software Revision:** The software has been revised to require a technician's reset (via the reset button on the board) after a second error (torque out). The control board can no longer be reset by unplugging the icemaker. This prevents frequent power resets without the technician's consent, which could result in damage to the icemaker.

Fig. 1





Fig. 2



Maestro is a trademark of Follett Corporation.
Follett is a registered trademark of Follett Corporation, registered in the US.